The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information							44-00-54 =	083-49-26 = -	
Michigan [26]	Arenac County [011]		Arenac [03360]	0.1 MI E OF HANS	0.1 MI E OF HANSEL			83.823889	
06302H00005B010 Highway agency district 4		Owner County Highway Agency [02] Maintenance responsibility		County Highway A	gency [02]				
Route 0 HICKORY ISLAND			Toll On fre	Toll On free road [3] Features intersected RIFLE RIVE			ER		
Design - Steel [3] main 1 Truss - Th	ru [10]	Design - approach O Other	r [00]	Kilometerpoint Year built 1920 Skew angle 0 Historical significan	Structure FI	constructed N/A	[0000]		
Total length 39 m = 128.0 ft Length of maximum span 39 m = 128.0 ft Deck width, out-to-out 6.1 m = 20.0 ft Bridge roadway width, curb-to-curb 5.2 m = 17.1 ft Inventory Route, Total Horizontal Clearance 5.2 m = 17.1 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft									
Deck structure type Type of wearing surface Wood or Timber [8] Bituminous [6]									
Deck protection Type of membrane/wearing surface									
Weight Limits									
Bypass, detour length 0.6 km = 0.4 mi Method to determine inventory rating Method to determine operating rating		Allowable Stress(AS) [2] Allowable Stress(AS) [2]		Inventory rating 3.6 metric ton = 4.0 tons Operating rating 7.3 metric ton = 8.0 tons					
	Bridge posting			Design Load M 9	/ H 10 [1]				

Functional Details									
Average Daily Traffic 160 Average daily tr	uck traffi 0 % Year 1998 Future average daily traffic 190 Year 2017								
Road classification Minor Collector (Rural) [08]	Lanes on structure 2 Approach roadway width 7.9 m = 25.9 ft								
Type of service on bridge Highway [1]	Direction of traffic 2 - way traffic [2] Bridge median								
Parallel structure designation No parallel structure	e exists. [N]								
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control								
Navigation vertical clearance 0 = N/A Navigation horizontal clearance 0 = N/A									
Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway 6.4 m = 21.0 ft									
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]									
Minimum lateral underclearance on right 99.9 = Unlimited Minimum lateral underclearance on left 0 = N/A									
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]									
Appraisal ratings - underclearances N/A [N]									
Repair and Replacement Plans									
Type of work to be performed	Work done by Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial	Bridge improvement cost 561000 Roadway improvement cost 30000								
bridge roadway geometry. [31]	Length of structure improvement 51.8 m = 170.0 ft Total project cost 591000								
	Year of improvement cost estimate 2005								
	Border bridge - state Border bridge - percent responsibility of other state								
	Border bridge - structure number								

Inspection and Sufficiency									
Structure status Posted for loa	ad [P]	Appraisal ratings - structural	Basically intolerable requiring	high priority of replacement [2]					
Condition ratings - superstructur Poor [4]		Appraisal ratings - roadway alignment	Better than present minimum	criteria [7]					
Condition ratings - substructure	Fair [5]	Appraisal ratings -	Basically intolerable requiring	high priority of replacement [2]					
Condition ratings - deck	Serious [3]	deck geometry							
Scour	Bridge is scour critical; bridge	Bridge is scour critical; bridge foundations determined to be unstable. [3]							
Channel and channel protection	Bank is beginning to slump. I minor stream bed movement	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]							
Appraisal ratings - water adequac	y Equal to present minimum cri	iteria [6]	Status evaluation	Structurally deficient [1]					
Pier or abutment protection			Sufficiency rating	15.1					
Culverts Not applicable. Used i	f structure is not a culvert. [N]								
Traffic safety features - railings									
Traffic safety features - transition	S								
Traffic safety features - approach	guardrail								
Traffic safety features - approach guardrail ends									
Inspection date October 2008 [1008] Designated inspection frequency 12 Months									
'	Not needed [N]	Underwater inspec							
·	Every year [Y12]	Fracture critical in:		[1007]					
Other special inspection	Not needed [N]	Other special insp	ection date						