HistoricBridges.org - National Bridge Inventory Data Sheet

The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information	33-31-16.30 = 090-11-02.90					
Mississippi [28] Leflore County [083]	Greenwood [29340] SEC 10 T19N R 1E 33.521194 = -90.184139					
SA420000000105 Highway agency district: 2	Owner City or Municipal Highway Agency [04] Maintenance responsibility City or Municipal Highway Agency [04]					
Route 1091 GRAND BLVD 9504 Toll On free road [3] Features intersected YAZOO RIVER						
main approach	year built 1925 Year reconstructed N/A [0000]					
Movable - Swing [17] 12 Te	e beam [04] Skew angle 0 Structure Flared					
	Historical significance Bridge is on the NRHP. [1]					
Total length 216.2 m = 709.4 ft Length of maximum span 44.6 m = 146.3 ft Deck width, out-to-out 7.9 m = 25.9 ft Bridge roadway width, curb-to-curb 7.6 m = 24.9 ft						
Inventory Route, Total Horizontal Clearance 7.5 m = 24.6 ft Curb or sidewalk width - left 2.4 m = 7.9 ft Curb or sidewalk width - right						
Deck structure type Concrete Cast-in-Place [1]						
Type of wearing surface Monolithic Concre	te (concurrently placed with structural deck) [1]					
Deck protection						
Type of membrane/wearing surface						
Weight Limits						
Bypass, detour length Method to determine inventory rat	ing Load Factor (LF) rating reported by rati Inventory rating 13 metric ton = 14.3 tons					
0.2 km = 0.1 mi Method to determine operating rat	ing Load Factor (LF) rating reported by rati Operating rating 21.4 metric ton = 23.5 tons					
Bridge posting 00.1 - 09.9 % b	Design Load MS 18 / HS 20 [5]					

Functional Details							
Average Daily Traffic 8500 Average daily tr	uck traffi 8 % Year 2013 Futu	ure average daily traffic	12750 Year 203	3			
Road classification Other Principal Arterial (Urban)	[14] Lanes on structure 2		Approach roadway wid	7.6 m = 24.9 ft			
Type of service on bridge Highway-pedestrian [5]	Direction of traffic 2 - way tra	ffic [2]	Bridge median				
Parallel structure designation No parallel structure							
Type of service under bridge Waterway [5]	Lanes under structure 0	Navigation control					
Navigation vertical clearanc 0 = N/A	Navigation horizonta	I clearance 0 = N/A					
Minimum navigation vertical clearance, vertical lift brid	dge	Minimum vertical cleara	nce over bridge roadway	4.03 m = 13.2 ft			
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]							
Minimum lateral underclearance on right 0 = N/A Minimum lateral underclearance on left 0 = N/A							
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]							
Appraisal ratings - underclearances N/A [N]							
Repair and Replacement Plans							
Type of work to be performed	Work done by Work to be done by contra	nct [1]					
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost 1315000	Roadway impi	rovement cost 13200	0			
	Length of structure improvement 22	21 m = 725.1 ft To	otal project cost 16210	00			
	Year of improvement cost estimate	2014					
	Border bridge - state	Boro	der bridge - percent respon	sibility of other state			
	Border bridge - structure number						

Inspection and Sufficiency					
Structure status Posted for lo	ad [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of replacement [2]		
Condition ratings - superstructure	ondition ratings - superstructure Fair [5]		Equal to present desirable criteria [8]		
Condition ratings - substructure	Fair [5]	Appraisal ratings -	Basically intolerable requiring high priority of replacement [2]		
Condition ratings - deck	Satisfactory [6]	deck geometry			
Scour	Bridge with "unknown" founda	tion that has not been ev	evaluated for scour. [U]		
Channel and channel protection	Bank is beginning to slump. Finding stream bed movement of	River control devices and evident. Debris is restrict	d embankment protection have widespread minor damage. There is cting the channel slightly. [6]		
Appraisal ratings - water adequac	Equal to present desirable crit	Equal to present desirable criteria [8] Status evaluation Structurally deficient [1]			
Pier or abutment protection			Sufficiency rating 34.2		
Culverts Not applicable. Used	if structure is not a culvert. [N]				
Traffic safety features - railings					
Traffic safety features - transition	ns				
Traffic safety features - approach	n guardrail				
Traffic safety features - approach	n guardrail ends				
Inspection date January 201	8 [0118] Designated inspe	ction frequency 24	4 Months		
Underwater inspection	Unknown [Y60]	Underwater inspec	ection date August 2015 [0815]		
•	Every two years [Y24]	Fracture critical ins	nspection date January 2018 [0118]		
Other special inspection Not needed [N] Other special inspection date					