

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

New York [36]	Warren County [113]	Warrensburg [78300]	1 MI NORTHWEST I87 EXIT24	43-36-34.85 = 43.609681	073-44-14.65 = -73.737403
3305150	Highway agency district: 17	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	CR10 TO RIVER RD	Toll On free road [3]	Features intersected	SCHROON RIVER	
Design - main 1	Steel [3] Truss - Thru [10]	Design - approach 0	Other [00]	Kilometerpoint 0 km = 0.0 mi	Year built 1896 Year reconstructed 1969
				Skew angle 0	Structure Flared
				Historical significance Historical significance is not determinable at this time. [4]	
Total length	27.1 m = 88.9 ft	Length of maximum span	26.5 m = 86.9 ft	Deck width, out-to-out	4.7 m = 15.4 ft
Bridge roadway width, curb-to-curb	3.8 m = 12.5 ft	Inventory Route, Total Horizontal Clearance	3.8 m = 12.5 ft	Curb or sidewalk width - left	0 m = 0.0 ft
				Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length	Method to determine inventory rating		Inventory rating	0 metric ton = 0.0 tons
0.3 km = 0.2 mi	Method to determine operating rating		Operating rating	0 metric ton = 0.0 tons
	Bridge posting		Design Load	

### Functional Details

Average Daily Traffic	162	Average daily truck traffi	10	%	Year	1983	Future average daily traffic	227	Year	2003
Road classification	Minor Collector (Rural) [08]		Lanes on structure	1		Approach roadway width	3.7 m = 12.1 ft			
Type of service on bridge	Highway [1]		Direction of traffic	1 - way traffic [1]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

### Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Bridge deck replacement with only incidental widening. [37]	Bridge improvement cost	1264000	Roadway improvement cost	740000						
	Length of structure improvement	27.1 m = 88.9 ft		Total project cost	2004000					
	Year of improvement cost estimate	2018								
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

## Inspection and Sufficiency

Structure status	<input type="text" value="Bridge closed to all traffic [K]"/>	Appraisal ratings - structural	<input type="text"/>
Condition ratings - superstructure	<input type="text" value="Imminent Failure [1]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text"/>
Condition ratings - deck	<input type="text" value="Critical [2]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="16"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="August 2018 [0818]"/>	Designated inspection frequency	<input type="text" value="12"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Every year [Y12]"/>	Fracture critical inspection date	<input type="text" value="August 2018 [0818]"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>